Con-Cast Zinc Alloy Bar Stock

Machining Guidelines

Eastern Alloys, Inc.

Henry Henning Drive - Maybrook, NY 12543

(845) 427-2151 FAX (845) 427-5185

www.eazall.com

Zinc Alloys have good Machinability – providing high quality and productivity over a wide range of machining conditions. Long tool life, low cutting forces, good surface finish and small chip formation are easily achieved.

GENERAL RECOMMENDATIONS								
Cutting Fluids	Cutting Tools	Speeds & Feeds						
 Always apply Generously Water-Based preferred, eg. 20:1 water- emulsifiable oil mixture. 	 Large, polished flutes Large rakes, clearances Sharp cutting edges Riged tool & work piece 	Moderate to highAvoid dwells in feed						

Note:

1.) The following recommendations were derived from studies using high-speed steel tools for machining ZA alloys in various cast forms. However they are also suitable for machining other zinc alloys castings, eg. Zamak alloys.

2.) The conditions presented are intended to give good overall results. If one aspect of machining requires optimization, other aspects may deteriorate. For example, optimum conditions for chip formation and cycle times (high speeds and feeds) are not the same as for optimizing surface finish, burr formation and tool life.

				С	OMMO	N OPERATIONS		
Drilling						Milling		
 Drill Design Fast spiral or polished general purpose jobber 118⁰ point angle 12⁰ to 14⁰ lip relief angle DO NOT grind flats on lips Speeds 200 to 300 ft/min (60 to 90 m/min) 						 Cutter Design End Milling – Right hand spiral flute geometry and special aluminum cutter design recommended. Plain Milling – "High Helix" and "Helical Aluminum" Milling Direction "Down" or "Climb" Milling 		
, , ,						Depth of Cut		
Feeds Diameter (in) Feed Rate	1/8	1/4 0.008	3/8 0.011	1/2	3/4 0.016	 0.125 in (3.18 mm) for roughing passes 0.025 in (0.64 mm) or less for finishing passes Speeds		
Deep Hole (Depth > 6X Drill Dia.) • Reduce feed and speed 50% • Intermittent withdrawl						 Up to 350 ft/min (100 m/min) for shallow depths of cut. Reduce speed for deep cuts, ie. As low as 100 ft/min (30 m/min) Feeds High table feeds preferred – 0.005 to 0.015 in/tooth (0.13 to 0.38 mm/tooth). Optimum feed rate should be determined by trial – depends on cutter dia, width and depth of cut, number of teeth, cutter speed and machine and workpiece rigidity. 		
Tapping Tap Design								
Spiral point for through holesStandard or special aluminum geometry for blind holes.				for blind	holes.	Reaming		
 Speeds Up to 200 ft/min (60 m/min) Reduce speed as thread pitch decreases 						 Reamer Design Common 6-fluted reamer recommended Both right hand spiral fluted and straight-fluted geometries acceptable. 		
 Form Tapping Preferred for small diameters Speed as for cutting tap 						Hole DiameterDrilled hole approximately 97% of reamer diameter		
Sawing						Speeds & Feeds		
Blade DesignCommon designs with raker set and standard tooth profile					Similar to those for drilling Reduce speed up to 50% for critical diameters			
• As coarse a blade as possible with at least 2 teeth in contact with workpiece.				ast 2 teeth	n in contact	Tool Design		
Speeds • 300 to 500 ft/min (90 to 120 m/min)						 10 to 15^o clearance angles 10 to 15^o positive back and side rake angles 		
 Feeds Vary with workpiece shape, blade geometry, surface finish requirements Moderate feed initially and adjust as required 				-	ace finish	Speeds & Feeds • 200 to 300 ft/min (60 to 90 m/min) Moderate feed rates – 0.010 in/rev (0.25 mm/rev) and depths of cut – 0.1 to 0.15 in. (2.5 to 3.8 mm)		

